



Preventiva

Consecutivo 27801
Representaciones Oil Filters S.A
Nit.: 830038805-8

Fecha 29/10/2022

Datos del Propietario o Tenedor del Vehículo

Table with vehicle registration details including Name (PALACIO LEON JOSE RAMON), Document Type (Cedula), Number (93296785), Direction (CR 53A 5:24), Phone (3102562955), City (Bogotá), Department (DISTRITO CAPITAL), Plate (LCO565), Brand (RENAULT), Company (EFFETRANS), Line (Duster), Class (Publico), Model (2023), Cylinder (1599), Service (Publico), License (10026120327), Fuel (GASOLINA), and Color (Amarillo).



Table with suspension and brake inspection criteria. Columns include suspension types (Delantera Derecha, Izquierda, Trasera Derecha, Izquierda) and brake types (Frenos, Desviación Lateral) with associated values and percentages.

Representaciones Oil Filter's S.A
NIT 830.038.805-8
Cra. 50 No. 2A-31
Tel: 202 4394 720 2720

Inspección Visual

Large table with 3 columns and 20 rows listing visual inspection items such as 'Identificación Reglamentaria', 'Luz de Parqueo', 'Eje 3 Llanta Izquierda', etc., with a 'Cumple' status for each.